



DIVERSIFIED
TESTING LABORATORIES, INC.
WORLDWIDE SERVICE

"We Test Per Your Request"

336 WEST FRONT STREET
P.O. BOX 4004
BURLINGTON, NORTH CAROLINA 27215
PHONE (336) 227-7710 • FAX (336) 227-1175
www.diversifiedtestinglabs.com

May 17, 2021

Mr. James Turner
FLAMEOFF COATINGS, INC.
1110 Navaho Drive
Suite 110
Raleigh, NC 27609

Reference: Laboratory Test Report
Lab Identification No. 45661
Invoice No. 76969

Dear Mr. Turner:

One (1) fabric sample, identified as **FlameOff FR Clear Woven Cotton**, was received and tested in accordance with CAN/ULC-S109-14, "Standard for Flame Tests of Flame-Resistant Fabrics and Films", Small-Flame Test. The results are as follows:

<u>Specimen Number</u>	<u>Test Results</u>		<u>Damaged Length (mm)</u>		
	<u>Residual Flame (sec)</u>	<u>Warp</u>	<u>Fill</u>	<u>Warp</u>	<u>Fill</u>
1	0.0	0.0	0.0	83	70
2	0.0	0.0	0.0	86	69
3	0.0	0.0	0.0	89	88
4	0.0	0.0	0.0	59	87
5	0.0	0.0	0.0	72	62
Avg.				77	

The fabric sample submitted **meets** the minimum requirements of the Small-Flame Test. The maximum average damaged length shall not exceed 165 millimeters and the maximum damaged length for any individual specimen shall not exceed 190 millimeters. No residues shall fall to the floor of the test chamber and continue flaming for more than two (2) seconds at any time during the test.

If there are any questions or when we can be of further assistance, please let us know.

Sincerely,

Brian S. Dement

BSD/mr

